

1 BEFORE THE ARIZONA CORPORATION CONVINCIONION **BOB STUMP** 2 Chairman Arizona Corporation Commission **GARY PIERCE** 3 DOCKETED Commissioner **BRENDA BURNS** 4 MAY 2 3 2014 Commissioner **BOB BURNS** 5 **DOCKETED BY** Commissioner SUSAN BITTER SMITH Commissioner 7 8 IN THE MATTER OF THE APPLICATION) DOCKET NO. G-01551A-10-0458 OF SOUTHWEST GAS CORPORATION DECISION NO. _**74499**_ 9 FOR APPROVAL OF ITS CUSTOMER OWNED YARD LINE SURCHARGE RATE. **ORDER** 10 11 12 13 Open Meeting 14 May 13 and 14, 2014 Phoenix, Arizona 15 BY THE COMMISSION: 16 17 **FINDINGS OF FACT**

1. Southwest Gas Corporation ("Southwest" or "Company") is engaged in providing natural gas service within portions of Arizona, pursuant to authority granted by the Arizona Corporation Commission.

18

19

20

21

22

23

24

25

26

27

28

- 2. On February 28, 2014, Southwest filed a request for approval of the Company's initial customer-owned yard line ("COYL") surcharge. Southwest's initial application requested a surcharge of \$0.00241 per therm, effective June 1, 2014. Subsequently Southwest indicated to Staff that it made corrections to the surcharge calculation, resulting in a revised requested surcharge level of \$0.00231 per therm.
- 3. Southwest's filing is pursuant to provisions contained in a settlement agreement approved by the Commission in Decision No. 72723 (January 6, 2012) to establish a COYL program that would survey existing COYLs and replace COYLs that were found to have leaks. A COYL is a

service line where the meter is generally located at the property line or public right-of-way, some distance from the customer premises, and the customer currently owns and is responsible for replacing/repairing the service line if there are any problems with it. Southwest no longer installs COYLs, but rather locates the meter at the building or structural wall of the customer premises. Customers may not properly maintain their COYLs or even be aware of their responsibility to maintain their COYLs, creating a potential safety hazard due to corrosion and leakage.

4. Under the COYL program approved in Decision No. 72723, Southwest was given \$1 million annually in base rates to acquire necessary leak detection equipment and conduct a leak detection survey of all the COYLs over a 3 year period. Southwest was also permitted to replace COYLs discovered through the COYL survey or from a leak survey following an odor call complaint and recover capital investment related to the COYL replacement program through a COYL cost recovery mechanism ("CCRM"), as detailed in the settlement agreement. The CCRM surcharge is not permitted to be greater than \$0.01 per therm in any single year and would be reset annually.

5. In Decision No. 74304 (January 29, 2014), the Commission expanded the COYL replacement program to allow COYL replacements to take place in coordination with other pipeline replacement projects, regardless of whether the COYL is leaking. However, Decision No. 74304 does not impact this filing, which only addresses COYL replacement activities through the end of 2013.

6. In Decision No. 73883 (May 8, 2013), the Commission approved Southwest's initial CCRM surcharge of \$0.00101 per therm, effective June 1, 2013. This surcharge was based upon total COYL spending of \$4.1 million in 2012.

7. Southwest's current filing requests approval of a surcharge of \$0.00231 per therm, effective June 1, 2014, based on reported COYL spending of \$5.8 million in 2013. This brings total COYL spending through the end of 2013 to \$9.8 million.

8. Under Decision No. 72723, Staff has 45 days from the date of Southwest's filing to make recommendations to the Commission regarding Southwest's filing.

Decision No. 74499

9. The table below shows information on the COYL program activities in 2012 and 2013.

_	
7	
_	

į		2012	2013
3	Total Lines Inspected or	52,243	51,432
4	Attempted to be Inspected		
	Lines Identified as Not Being	14,456	6,168
5	Eligible Under the COYL		
	Program		
6	Lines Identified as COYLs	37,787	45,264
7	Number Passing the Survey	25,147	22,106
	Number Identified as Leaks	1,913	1,967
8	Number Refusing to allow	1,479	5,053
	Southwest to Survey		
9	Number Southwest was	9,248	15,990
Ť	Unable to Contact		
10	Number of COYLs Replaced	1,767	2,236
11	Replacements in Progress at	37	15
	the Time of Southwest's Filing		
12	Number Undecided as to	40	140
	Whether to Replace		
13	Number Declining	69	90
	Replacement of Leaking		
14	COYL		

NOTE: In 2013, Southwest also had 404 COYLs that were identified as previously passing the survey, declined a leak survey, or did not respond to efforts by Southwest to communicate with them, but in 2013 had leaks discovered. There were also 110 relocations in 2013 that were identified as "in progress" in 2012, was undecided in 2012, or previously had declined a relocation but reconsidered.

- 10. Southwest has indicated that 19,190 known COYLs remain in Arizona to be inspected in 2014 (not counting those for which Southwest has attempted to survey but has been unable to in 2012 and 2013). The initial round of inspections was expected to take place in three years and thus Southwest appears to be on or ahead of schedule to complete all inspections (apart from those COYLs it has been unable to gain access to to inspect) within the initial three year period of the COYL program.
- 11. At the time the Commission reviewed Southwest's CCRM surcharge filing a year ago, Southwest estimated that there were 118,500 COYLs in Southwest's Arizona service territory.
- 12. Southwest now estimates that there are a total of 98,303 COYLs that have been replaced (4,003) or remain to be replaced assuming customer consent (94,300). Southwest now estimates that the COYL program would cost \$240,835,453 to replace all COYLs in its Arizona service territory.

Decision No. __74499

. . .

- 13. When reviewing last year's COYL filing, Staff expressed concern with the high percentage of customers with COYLs who did not have their COYLs inspected either because Southwest was unable to contact them or that the customer refused to allow Southwest to inspect the COYL. In Decision No. 73883, the Commission ordered Southwest to submit a plan within 90 days of the Commission's decision in the proceeding, aimed at increasing customer response and participation in the COYL inspection process.
- 14. On August 6, 2013, Southwest filed its Customer-Owned Yard Line Response and Participation Plan. Southwest has indicated to Staff that in 2013 it implemented a telephone outreach effort with live telephone contact to try to improve participation. Southwest continues to have a significant number of customers whose COYLs it is unable to survey. Southwest also has indicated that in the 2nd quarter of 2014 the Company will put COYL program information on its website for customers to access.
- 15. Southwest is seeking recovery of \$5,768,730 in gross COYL plant installed in 2013. Thus, the total gross plant installed under the COYL program to date is approximately \$9.8 million (\$4.1 million in gross plant was installed in 2012). Staff has reviewed the 2013 costs and held discussions with Southwest regarding these costs and believes that these costs are reasonable to include for recovery through the CCRM surcharge.
- 16. Given the \$5.8 million cost in 2013 and the COYLs replaced under the program, the total cost per COYL replaced is approximately \$2,450 per COYL replaced in 2013. This is an increase from a cost of approximately \$2,300 per COYL replaced in 2012. Southwest has indicated that the cost increase per replacement in 2013 is a result of more COYL survey activities in rural areas and the resulting longer service line lengths and more difficult digging conditions.
- 17. Staff has recommended approval of the \$0.00231 per therm CCRM surcharge, effective for 12 months, beginning on June 1, 2014.

CONCLUSIONS OF LAW

1. Southwest Gas Corporation is an Arizona public service corporation within the meaning of Article XV, Section 2, of the Arizona Constitution.

Decision No. 74499


ORDER

IT IS THEREFORE ORDERED that Southwest Gas Corporation's application for a CCRM surcharge of \$0.00231 per therm, effective for 12 months, beginning on June 1, 2014, be and hereby is approved.

IT IS FURTHER ORDERED that this decision shall become effective immediately.

BY THE ORDER OF THE ARIZONA CORPORATION COMMISSION

SSIONER COMMISSIONER COMMISSIONER



JODI JERICH EXECUTIVE DIRECTOR

DISSENT:

DISSENT:

SMO:RRG:sms\RRM

Decision No. _74499

Docket No. G-01551A-10-0458

28

20

21

22

23

24

25

26

27